

FIGURE 3.-SIMULATED DECLINE IN THE ALTITUDE OF THE POTENTIOMETRIC SURFACE OF THE EVANGELINE AQUIFER DUE TO PUMPING, 1890-1980 AND RECHARGE BY WELLS, 1973-80




FIGURE 4.-DECREASE IN THE DECLINE OF THE ALTITUDE OF THE POTENTIOMETRIC SURFACE OF THE EVANGELINE AQUIFER DUE TO RECHARGE BY WELLS, 1973-80

